

UTTARAKHAND POWER CORPORATION LTD

Urja Bhawan, Kanwali Road, Dehradun-248 001
Tel.0135-2768876, Fax No.0135-2763570/2768867
EPBX No. 0135-2763672-73-74-75 Extn. -102/116



mRrjk[kM ikoj dkjikjksku fy0
Å t k Hkou] dkoyh ekx] ngjknw&248 001
rjg Hkk'k %0135&2768876 QDI % 0135&2763570@2768867
i hch, DI & 0135&2763672&73&74&75 foLrkj 102@116

i = 1 0 % 1722

@fu% fj-%@mi kdkfy@ , l &2

fnukd% 28-06-2008

Subject: Instruction No.13 : Regarding Submission of Daily Feeder Outage Report w.e.f. 01.07.2008.

Sri
Sub-Divisional Officer,
Electy. Distbn. Sub-Division,
Uttarakhand Power Corporation Ltd.,
.....

For computation of Consumer Reliability Index it is felt necessary to know the Daily Feeder-wise detailed outage position

In view of the above, you are hereby instructed to submit 33 KV/ 11 KV Feeder-wise Daily Outage Report in respect of your Sub-Division on the prescribed format enclosed herewith.

This information, duly filled in properly every column of the format, has to be submitted to UPCL Information Centre functioning at Urja Bhawan, Dehradun, w.e.f. 01.07.2008 on Fax No.0135-2763821 and/or on email: dgmpm@uttaranchalpower.com regularly upto 11.30 A.M. every day with feeder-wise detailed reasons/remark of outage of the feeders.

Encl: As above.

(J.M. LAL)

DIRECTOR (OPERATION)

i = 1 0 % 1722 @fu% fj-%@mi kdkfy@ , l &2

fnukd% 28-06-2008

Copy, along with a copy of enclosure, forwarded to the following for information and ensuring strict compliance of the above instructions. It may please also be ensured at their level that copy of above instructions are made available to each and every S.D.O. of their Zone/Circle/Division :

1. General Manager(D), UPCL, Garhwal / Kumaun Zone, Pauri/Haldwani.
2. Dy.General Manager, E.D.C., UPCL, Dehradun(Urban)/ Dehradun (Rural)/ Roorkee/Srinagar(G)/Rudrapur/Haldwani/Ranikhet.
3. Executive Engineer, Electy. Distbn. Division, UPCL,

Encl: As above.

(J.M. LAL)
DIRECTOR (OPERATION)